	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm
1	BRS	L1		single adj2 (phase or coil or winding)		2005/01/ 28 08:10	
2	BRS	L2	8590	brushless	į.	2005/01/ 28 08:10	
3	BRS	L3	2142 7	bobbin		2005/01/ 28 08:10	
4	BRS	L4	87	1 and 2 and 3		2005/01/ 28 08:10	